



State of Utah  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt  
Governor

Ted Stewart  
Executive Director

James W. Carter  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340  
801-359-3940 (Fax)  
801-538-5319 (TDD)

May 31, 1994

TO: Minerals File

FROM: Travis Jones, Reclamation Hydrologist *TWJ*

RE: Site Inspection, Ashgrove Cement Company, Nielson Sandstone Quarry,  
M/023/012, Juab County, Utah

Date of Inspection: May 23, 1994

Time of Inspection: 1400-1415

Conditions: Sunny and warm

Participants: Rody Cox--BLM; Wayne Hedberg and Travis Jones--DOGM

Purpose of Inspection: Inspect current disturbance

While in the area of this operation with the BLM, we decided to stop by the site and examine the current disturbance. The operation was active during our inspection. A front-end loader was loading stockpiled and loose processed sandstone ore onto tandem haul trucks, which were transporting the ore to the Leamington Cement Plant. The extent of disturbance was visually estimated at approximately six acres. The highwall presently stands roughly 40-60 feet in height. Photographs were taken of the site from the top of the southwest highwall for the BLM. We have similar file photos from a 4/6/94 site inspection.

jb

cc: Rody Cox, House Range RA, BLM  
Andrew Robinson, Ashgrove Cement Company  
M023012.ins





